

## Tabla de Conversiones

FRACCIÓN	DECIMAL	MM
1/64	0.0156	0.3968
1/32	0.0312	0.7937
3/64	0.0468	1.1906
1/16	0.0625	1.5875
5/64	0.0781	1.9843
3/32	0.0937	2.3812
7/64	0.1093	2.7781
1/8	0.1250	3.1750
9/64	0.1406	3.5718
5/32	0.1562	3.9687
11/64	0.1718	4.3656
3/16	0.1875	4.7625
13/64	0.2031	5.1593
7/32	0.2187	5.5562
15/64	0.2343	5.9531
1/4	0.2500	6.3500
17/64	0.2656	6.7468
9/32	0.2812	7.1437
19/64	0.2968	7.5406
5/16	0.3125	7.9375
21/64	0.3281	8.3343
11/32	0.3437	8.7312
23/64	0.3593	9.1281
3/8	0.3750	9.5250
25/64	0.3906	9.9218
13/32	0.4062	10.3187
27/64	0.4218	10.7156
7/16	0.4375	11.1250
29/64	0.4531	11.5093
15/32	0.4687	11.9062
31/64	0.4843	12.3031
1/2	0.5000	12.7000
33/64	0.5156	13.0968
17/32	0.5312	13.4937
35/64	0.5468	13.8906
9/16	0.5625	14.2875
37/64	0.5781	14.6843
19/32	0.5937	15.0812
39/64	0.6093	15.4781
5/8	0.6250	15.8750
41/64	0.6406	16.2718
21/32	0.6562	16.6687
43/64	0.6718	17.0656
11/16	0.6875	17.4625
45/64	0.7031	17.8593
23/32	0.7187	18.2562
47/64	0.7343	18.6531
3/4	0.7500	19.0500
49/64	0.7656	19.4468
25/32	0.7812	19.8437
51/64	0.7968	20.2406
13/16	0.8125	20.6375
53/64	0.8281	21.0343
27/32	0.8437	21.4312
55/64	0.8593	21.8281
7/8	0.8750	22.2250
57/64	0.8906	22.6218
29/32	0.9062	23.0187
59/64	0.9218	23.4156
15/16	0.9375	23.8125
61/64	0.9531	24.2093
31/32	0.9687	24.6062
63/64	0.9843	25.0031
1	1.0000	25.4000